

40 C.F.R. § 63.7922

How do I demonstrate continuous compliance with the work practice standards for equipment leaks?

- (a) You must demonstrate continuous compliance with the emissions limitations and work practice standards in § 63.7920 applicable to your affected equipment by meeting the requirements in paragraphs (b) through (d) of this section that apply to you.

This document is only available to subscribers. Please log in or purchase access.

[Purchase Login](#)