

40 C.F.R. § 63.9302

What operating limits must I meet?

(a) For any new or reconstructed affected source on which you use add-on controls, you must meet the operating limits specified in Table 2 to this subpart. These operating limits must be established during the performance test according to the requirements in § 63.9324. You must meet the operating limits at all times after you establish them.

This document is only available to subscribers. Please log in or purchase access.

Purchase Login