

29 C.F.R. § 1915.15

Maintenance of safe conditions.

- (a) *Preventing hazardous materials from entering.* Pipelines that could carry hazardous materials into spaces that have been certified “Safe for Workers” or “Safe for Hot Work” shall be disconnected, blanked off, or otherwise blocked by a positive method to prevent hazardous materials from being discharged into the space.
- (b) *Alteration of existing conditions.* When a change that could alter conditions within a tested confined or enclosed space or other dangerous atmosphere occurs, work in the affected space or area shall be stopped. Work may not be resumed until the affected space or area is visually inspected and retested and found to comply with §§ 1915.12, 1915.13, and 1915.14 of this part, as applicable.

This document is only available to subscribers. Please log in or purchase access.

[Purchase Login](#)