

29 C.F.R. § 1926.913

Blasting in excavation work under compressed air.

- (a) Detonators and explosives shall not be stored or kept in tunnels, shafts, or caissons. Detonators and explosives for each round shall be taken directly from the magazines to the blasting zone and immediately loaded. Detonators and explosives left over after loading a round shall be removed from the working chamber before the connecting wires are connected up.

This document is only available to subscribers. Please [log in](#) or [purchase access](#).

[Purchase Login](#)