

40 C.F.R. § 80.1477

Requirements for QAPs for biointermediate producers.

- (a) Independent third-party auditors that verify biointermediate production must meet the requirements of § 80.1471(a) through (c) and (f) through (h), as applicable.
- (b) QAPs approved by EPA to verify biointermediate production must meet the requirements in § 80.1469(c) through (f), as applicable.

This document is only available to subscribers. Please log in or purchase access.

Purchase Login